	Laurel Run System #1	Laurel Run System #2
General Project Information		
Project Name & #	Laurel Run #1	Laurel Run #2 PA-128
Location:	•	111 120
Municipality	Center Township	Center Township
County	Indiana	Indiana
Watershed:	Blacklick Creek	Blacklick Creek
USGS Quad	New Florence	New Florence
Lat	?	40.4941167
Long	?	-79.121944
Contact Info		
Contact Organization:	Blacklick Creek Watershed	Blacklick Creek Watershed
	Association	Association
Contact Person:	Bob Eppley	Bob Eppley
Contact Address:	52 Oakland Ave	52 Oakland Ave
	Homer City, PA 15748	Homer City, PA 15748
Contact Phone Number:	412-289-2857	412-289-2857
Contact email:	eppldr@msn.com	eppldr@msn.com
Organization Currently Responsible For Project Operations, Monitoring and Maintenance	Same as above	Same as above
Site Information		
Who owns the property the project is constructed upon?	PA Game Commission	James Rhine
Driving Directions to the Project Site:		
Special Instructions for entry to the site (gates, keys, notifications, or permissions, etc.)?	The road to the site is gated. Contact the Game Commission for the key.	Road is gated and owner must be contacted. BCWA has a key to the site.
Is there a perpetual access agreement for monitoring and O&M? Y/N	?	?
Is the site accessible by 2WD vehicle? Y/N	Yes	Yes
Was the project completed as part of an overall watershed restoration plan? Y/N	Yes	Yes
Is the plan available electronically?	No	No

	Laurel Run System #1	Laurel Run System #2
Could you provide the DEP a copy of the plan?	DEP has a copy of it.	DEP has a copy of it.
Is a copy of the plan attached? Y/N	No	No
Project Description (Describe the treatment system including each individual component):	Passive treatment system Pond 1 – VFR A Pond 2 - VFR B Pond 3 – Settling pond/wetland	Sulfate reducing bacteria passive treatment system Pond 1 – VFR A Pond 2 – VFR B Pond 3 – Selling pond Pond 4 - Wetland
Pre-Construction Discharge Flow & Monitoring Data		
Is data available electronically? Y/N	AStream Restoration, Inc. and DEP	Yes
In what format?	?	Excel
Indicate how flow was measured?	?	Unknown
Laboratory used or field kits:	?	DEP Lab & Operation Scarlift
Could you provide this data to the DEP? Y/N	No The DEP should have data.	Yes
Is a copy of the data attached? Y/N	No	No
Pre-Construction Receiving Stream Flow & Monitoring Data		
Is data available electronically? Y/N	Stream Restoration and the DEP	Yes
In What format?	?	Excel
Indicate how flow was measured:	?	Unknown
Indicate laboratory that analyzed samples (or whether field kits were used):	DEP Lab and field tests	DEP Lab & Unknown
Were any biological or fish surveys completed? Y/N	No	Unknown
Could you provide this data to the DEP? Y/N	NA	No
Is a copy of the data attached? Y/N	No	No
Treatment System Design Info & Criteria		


Laurel Run System #1	Laurel Run System #2
zauter zum System ii I	R. Eppley
	and
Stream Restoration Inc.	L. Robert Kimball & Assoc.
	615 W. Highland Ave.
, <u> </u>	Ebensburg, PA 15931
*	814-472-7700
sil@streamrestorationinc.org	
į.	minned@lrkimball.com
Vaa	Dave Minnear
res	Yes
Yes	Yes
	95% reduction of parameters
90 gpm	200 gpm
?	?
All	All
SRI	L. Robert Kimball & Associates,
DIG.	Inc.
No	Yes
110	103
No	No
INO	NO
CDI	V 7
SKI	Yes
	77 7 7 1 . 77 1 . 1
No	Yes – L. Robert Kimball and
	Associated, Inc.
No	No
?	2005
?	6/2005
	? All SRI No No SRI No No SRI No ?

	Laurel Run System #1	Laurel Run System #2
When (specific date) was project	SRI for info	11/2005
construction completed?	G	
Who was the construction	?	Robindale Energy Services
contractor? (Name, address,	·	224 Grange Hall Road
Phone, email, contact person)		Amaugh, PA 15920
indie, email, editate person)		814-446-6700
		7
		Jim Panaro
When (specific date) did the	?	11/20/2005
treatment system go on-line?	•	11,20,200
deament by stem go on mic.		
Primary I	Funding Partners, and funding pr	ovided:
Source	Amount	
Title IV, Appalachian Clean	\$0.00	\$287,021.00
Streams		
PADEP Growing Greener	\$0.00	\$0.00
10% AMD Set Aside Funds	\$0.00	\$0.00
EPA Section 319	\$0.00	\$0.00
OSM Watershed Cooperative	\$0.00	\$0.00
Assistance Program	·	
NRCS	\$0.00	\$0.00
EPA Watershed Protection	\$0.00	\$0.00
USCOE	\$0.00	\$0.00
University	\$0.00	\$0.00
Private/Foundation	\$0.00	\$0.00
211, 000, 2 0 0220012012	\$ 3,700	
How or by whom was treatment	?	?
system construction funded or		
other funding not included in the		
table. (Source, Amount)		
Post Construction Operation,		
Monitoring and Maintenance		
Is there a sampling and	Unknown	Unknown
monitoring plan? Y/N		
Is a copy of the plan available	Unknown	Unknown
electronically? Y/N		
Is a copy of the plan attached?	No	No
Y/N		
Is treatment system currently	Yes	Yes
being sampled and monitored?		
Y/N		
If so, by whom?	Stream Team	DEP
Approximately how many hours	BCWA – O & M	BCWA – O & M
per year are spent doing O,M&M	50 hours/yr	60 hours/yr
for this system?		

	Laurel Run System #1	Laurel Run System #2
Where are the samples being	DEP Lab	DEP Lab
analyzed? (Name, Address,	DET East	DLI Lau
Phone, email, contact person)		
If DEP Lab is being used, what is	Project Id:KCRBWMN	Unknown
the project ID and the Sample	Sequence No.: 458, 459, 460 &	The DEP is monitoring the
Information System (SIS)	461	systems.
monitoring point IDs?	Monitoring Point No.:KBLLR1,	systems.
S F common and a c	KBLLRA, KBLLRB, &	
	KBLLRE	
Is there an Operation and	BCWA inspects weekly and	BCWA inspects weekly and
Maintenance Plan? Y/N	measures the pH	measures the pH
Is the plan available	No	No
electronically? Y/N		
Could you provide the DEP a	No	No
copy of this information? Y/N		
Is a copy of the information	No	No
attached? Y/N		
Comments on the treatment	Has been rebuilt once	Source split to two systems
system:		
Post-Construction Discharge		
Flow and Monitoring Data		
Is the data available	Yes	DEP is sampling.
electronically? Y/N		
In what format?	Excel	Unknown
Indicate how the flow was	Bucket and stopwatch	Unknown
measured:		
Could you provide the DEP a	Yes	DEP has the data.
copy of this information? Y/N		
Is a copy of the information	No	No
attached? Y/N		
Post-Construction Receiving		
Stream Flow and Monitoring		
Data		
Is the data available	No	DEP is sampling
electronically? Y/N		DDI to builpring
In what format?	NA	Excel
Indicate how the flow was	NA NA	DEP measured the flow
measured:		
Could you provide the DEP a	NA	DEP has the info
copy of this information? Y/N		
Is a copy of the information	No	No
attached? Y/N		
Were any biological or fish	No	No
surveys that were completed on		
the receiving stream? Y/N		


	Laurel Run System #1	Laurel Run System #2
Treatment System Maintenance and /or Rehabilitation		<u> </u>
Has rehabilitation work been performed at the site? Y/N	Yes	No
If yes, please list the rehabilitation activity.	Refurbished the organic layer	NA
If yes, please list the date rehabilitation	June, 2008	NA
If yes, please list the rehab cost.	BCWA provided the funds	NA
What routine or non-routine maintenance issues have arisen since system was put online?	Cracking of organic layer after valves adjusted	None
How was maintenance work funded?	BCWA provided the funds	None
What maintenance is needed or anticipated in the next 1-3 years?	None	None
Other Comments		
Person(s) Completing form:	Dennis Remy	Dennis Remy
Name	5320 Ferguson Road, Indiana, PA	5320 Ferguson Road, Indiana,
Address	15701	PA 15701
Phone	724-349-8597	724-349-8597
Email	Dennisr3@comcast.net	Dennisr3@comcast.net
Date Completed		
Any other contact?	Bob Eppley	Bob Eppley

Laurel Run Passive Treatment System #1 Sample Location Map



400

Laurel Run Passive Treatment System #1 Site Map



Laurel Run Passive Treatment System #2 Site Map





LEGEND

- Discharge Sample Location
- Treatment Sample Location
- Stream Sample Location

8